









3AS





x1



x2




x16



x1




x4



x2



x2



FU8x50 x4



3,5x32 x2



3,5x9,5 x6



4,5x60 x4



M3x6 x8



x6



x4




x2



x2



x2







x2




x2

3AS	P	L1-L2 mm
117	1180-1200	1170-1190
119	1200-1220	1190-1210
121	1220-1240	1210-1230
125	1260-1280	1250-1270
127	1280-1300	1270-1290
129	1300-1320	1290-1310
131	1320-1340	1310-1330
135	1360-1380	1350-1370
137	1380-1400	1370-1390
139	1400-1420	1390-1410
141	1420-1440	1410-1430
145	1460-1480	1450-1470
147	1480-1500	1470-1490
149	1500-1520	1490-1510
151	1520-1540	1510-1530
155	1560-1580	1550-1570
157	1580-1600	1570-1590
159	1600-1620	1590-1610


3AS	V	L1-L2 mm
117	1157-1177	1170-1190
119	1177-1197	1190-1210
121	1197-1217	1210-1230
125	1237-1257	1250-1270
127	1257-1277	1270-1290
129	1277-1297	1290-1310
131	1297-1317	1310-1330
135	1337-1357	1350-1370
137	1357-1377	1370-1390
139	1377-1397	1390-1410
141	1397-1417	1410-1430
145	1437-1457	1450-1470
147	1457-1477	1470-1490
149	1477-1497	1490-1510
151	1497-1517	1510-1530
155	1537-1557	1550-1570
157	1557-1577	1570-1590
159	1577-1597	1590-1610




1




x2




2





x2








x2



3




4







5

5








-   M5 x1
-  M5x8 x1
-  M5x10 x1
-  M5x16 x1




-  S6 x2
-  4x35 x2
-  ø6 mm

6




7




x4



7.1 x4




7.2 x4




M3x6 x4

8




x2




No!


OK




x2




9



x4




x4




M3x6 x4


x16




10








x2





x2



11





12







3,5x9,5 mm x2

x2



13



14








15




3,5x9,5 mm x4

x4


16




17




x2




x2




18




x2




x2





19




x2




x2







20






x2



21





22



A1/A2

23



24

